

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
Campbell Hausfeld and Husky Air Compressors	Protective covers on the compressor's motor are not made from proper flame retardant material and can ignite, posing a fire hazard to consumers.	Consumers should stop using the air compressor immediately and contact Campbell Hausfeld for a free repair kit.	The recall involves the following Campbell Hausfeld and Husky brand air compressors: Capacity Model Numbers Serial Numbers 8-15 gallon HL410100, HL421000 HL421500, HL431500 The first four digits of the serial number indicate a date code from July 2005 (0705) through March 2007 (0307) 4 gallon HL5402 Have a prefix of HY, KB, or HU followed by a date code from November 2006 (1106) through November 2007 (1107)	Campbell Hausfeld, of Harrison, Ohio	September 2005 through November 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08181.html			
Reading and Math Aids	Surface paint on the products contains excessive levels of lead, violating the federal lead paint standard.	Consumers should immediately take the recalled products away from children and contact RR Donnelley for information on returning the products for a free replacement item. RR Donnelley is directly contacting schools that purchased the reading and math aids	Magnetic Dry-Erase Board 0076176266 The magnetic dry-erase boards have purple plastic frames. "SRA" logo is printed on the front of the boards. There are permanent squares imprinted on the face of each side of the board. Sold in a set of five. They measure 8 1/2" x 11". Student Crown 0026612887 The crowns are red, purple and gold with a thinking bubble in the middle. They were sold in packages of 12. The crown's two ends close with Velcro to create a hat-like crown for students. Puppet Thinking Crown 0812603575 The crowns are red, purple and gold with a thinking bubble in the middle. The two ends close with Velcro to create a hat-like crown the teacher's puppet wears. Includes a chin strap. The crown measures 16" long x 5" wide with a clear pocket on the front of the crown. Angled Ruler 002674452X The clear plastic rulers are 12 inches long, bend in the middle, and have green imprints. Sold in packs of 10. Magnetic Number Line R00006029 The magnetic number lines are white, about 23 inches long,	SRA, of Columbus, Ohio, Glencoe, of Columbus, Ohio, and Wright Group, of Chicago, Ill.	July 2003 through October 2007.	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08541.html			
Crafters Square Hot Melt Mini Glue Guns	The recalled glue guns can short circuit, causing the gun to smoke and catch fire. This poses fire, burn and shock hazards to consumers.	Consumers should immediately stop using the recalled glue guns and return them to the store where purchased for a full refund.	The glue guns dispense hot glue and are intended for craft projects. The recalled glue gun is black with a yellow trigger and is approximately 4 1/2 inches from the back of the gun to the tip. Attached is a 44-inch electrical cord. "Crafters Square" and product number 818261-72 or 818261-75 are located on the guns' packaging.	Dollar Tree, Dollar Bill\$, Dollar Express, Greenbacks, Only One \$1, and Deal\$ stores nationwide	February 2007 through August 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08175.html			

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
Serene Float Tanks	Electrical components in the float tank are not grounded, which can prevent the Ground Fault Circuit Interrupter (GFCI) from tripping when needed, posing an electrocution hazard to consumers.	Consumers should immediately stop using the recalled float tanks and contact Brian Smith for a refund.	This recall involves Serene Float Tanks, a water tank that is light- and soundproof, temperature insulated and ventilated. The heated tanks are filled with water and a dissolvent that allows a person to float effortlessly.	Brian Smith, dba Serene Float Tanks, of Lakewood, Calif.	August 2007 and October 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08540.html			
ESI-R Screening Materials	Surface paint on the green wooden blocks contains excessive levels of lead, violating the federal lead paint standard.	Purchasers should immediately stop using the blocks in the ESI-R Screening Materials. RR Donnelley will provide free replacement materials and instructions for returning the recalled product. RR Donnelley is directly contacting purchasers and posting information on its Web site.	The green wooden blocks are part of the ESI-R Screening Materials, educational materials used by schools to assess young children. The items include 10 green wooden blocks, a plastic yellow car, an 8-ft. white cloth ribbon, 10 black and white printed cards with shapes, a red rubber ball, and a blue plastic button.	Pearson Learning Group, and Pearson Early Learning, of Upper Saddle River, N.J.	January 2003 through November 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08539.html			
John Deere Compact Utility Tractors	The forward drive pedal can get stuck, posing a risk of loss of control and injury to the operator and bystanders.	Consumers should stop using the recalled vehicles immediately and contact any John Deere dealer to schedule a free repair. Registered owners were sent direct mail notification of this recall.	The recalled tractor is model number 3203, which is painted on the side of the tractor. The recall includes the following serial numbers: LV3203H000001 through LV3203H000010 LV3203H190001 through LV3203H193434 LV3203H393093 LV3203H394001 through LV3203H396669 The serial number plate is located on the tractor's frame above the right front wheel.	Deere & Company, of Moline, Ill.	September 2005 through December 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08536.html			
"BabyTown" Pacifiers	These pacifiers fail to meet federal safety standards for pacifiers. The pacifier shield is too small and could easily enter the mouth of an infant. Also, ventilation holes are too small and not placed to allow for the insertion of a tool to remove the pacifier when lodged in the mouth of a child. Finally, the package fails to display the required warning instructing consumers not to tie a pacifier around a child's neck, which would present a strangulation hazard.	Consumers should take these pacifiers away from children immediately and return them to the store where purchased for a full refund.	The recalled pacifiers were sold in a 4-pack of assorted colors. "BabyTown" and model #39864 are written on the product's packaging.	Shims Bargain Inc., of Los Angeles, Calif.	March 2004 through December 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08160.html			
Portfolio Incandescent Torchere Lamps	A short circuit in the lamps' wiring can pose a fire hazard to consumers.	Consumers should immediately stop using the recalled lamps and return them to any Lowe's retail outlet to receive a refund.	The recalled lamp has a black steel frame and a bowl-shaped light fixture. The item number 179878 is printed on the packaging and the bottom of the base of the lamp. Only lamps sold between March 2005 and October 2007 with UL listing number E246506 are included in the recall. Lamps marked "ETL listed" are not included in the recall.	L G Sourcing, Inc., of North Wilkesboro, N.C.	March 2005 through October 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08159.html			

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
Intermatic DT27 Digital Self-Adjusting Timers	The recalled timers could have been wired incorrectly, which poses an electrical shock hazard to consumers.	Consumers should stop using the recalled timer immediately and unplug before checking the model number and date code. Consumers should contact Intermatic to return the timer and obtain a free replacement.	This recall involves the Intermatic DT27 digital self-adjusting timer with a date code of "04B." This product is a lamp and appliance timer and is packaged as either the "DT27C Heavy Duty Digital Timer" or the "DT27CL Time All® Digital Lamp and Appliance Self-Adjusting Timer." The timer is white with a rounded top, and measures 3 7/8" tall by 2 3/4" wide by 1 5/8" deep. The brand name "Intermatic" is molded on the front of the timer, and the model number ("DT27") and date code ("04B") are printed on the back of the timer.	Intermatic Inc., of Spring Grove, Ill.	February 2007 through December 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08157.html			
Model Year 2007 Honda TRX 500 ATVs	Water can enter the throttle position sensor and freeze, causing permanent damage if the rider forces the throttle lever. This could cause the throttle to stick open, posing a risk of injury or death to riders.	Consumers should immediately stop using these recalled ATVs and contact any Honda ATV dealer to schedule a free repair. Registered owners of the recalled ATVs have been sent direct notice.	This recall involves Model Year 2007 Honda TRX 500 ATVs, also known as the Honda Foreman and Foreman Rubicon. The adult-size ATVs are designed for use by riders age 16 and older. The 2007 model year ATVs are available in red, black, blue, olive, and camouflage. The Honda name and wing logo are printed on the fuel tank and the model name is printed on the side panel just below the seat.	American Honda Motor Co., Inc. of Torrance, Calif.	June 2006 through December 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08535.html			
2006-2008 Model Year MXU 500 All Terrain Vehicles	The pivot bolts holding the rear suspension onto the frame can become loose, causing the rear swing arm to detach from the chassis posing a risk of injury or death to the operator.	Consumers should immediately stop using the recalled ATVs and contact an authorized KYMCO dealer in their area to schedule a free repair. Registered owners were sent direct mail notification of this recall.	This recall involves all model year 2006-2008 MXU 500 ATVs. The vehicle is identified by a label on the front as KYMCO and the model is determined by a label located on each side of the fuel tank as MXU 500.	KYMCO USA, of Spartanburg, S.C.	November 2006 through December 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08532.html			
Sketchbooks with Colored Spirals	The paint on the sketchbooks' colored spiral metal bindings contains excessive levels of lead violating the federal lead paint standard.	Consumers should immediately take the recalled sketchbooks away from children and contact eeBoo Corp. to receive a free replacement sketchbook with a plain metal spiral.	The recalled children's sketchbooks have colored spiral metal bindings, drawing paper, and cardboard covers in the following styles. "eeBoo" and the style name are printed on a sticker on the back cover. Style Name Size Drawing Birds (yellow spiral) 8 ½" x 11 ½" "eeBoo Great Illustrators Sketchbook" is printed on front cover Butterflies (yellow spiral) 8 ½" x 11 ½" "eeBoo Great Illustrators Sketchbook" is printed on front cover Garden Party (green spiral) 8 ½" x 11 ½" "eeBoo Great Illustrators Sketchbook" is printed on front cover Up in the Tree (green spiral) 8 ½" x 11 ½" "eeBoo Great Illustrators Sketchbook" is printed on front cover Nemo with Princess in Balloon (red spiral) 8 ½" x 11 ½" "Sketchbook" is printed on front cover Nature (yellow spiral) 8 ½" x 11 ½" "eeBoo Great Illustrators Sketchbook" is printed on front cover Princess and Butterflies (yellow spiral) 8 ½" x 11 ½" "Sketchbook" is printed on front cover Princess and Butterflies (yellow spiral) 10" x 14" "Sketchbook" is printed on front cover	eeBoo Corp., of New York, N.Y.	September 2005 through January 2008	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08184.html			

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
GE Gas Clothes Dryers	short circuit in the dryer's wiring poses a shock hazard to consumers with ungrounded dryers.	Consumers should stop using the recalled dryers immediately, unplug the dryer, and contact GE for further instructions and to schedule a free, in-home inspection and repair. GE is directly contacting consumers who purchased the recalled dryers.	The recalled gas dryers are 42 inches tall (back with backsplash) and 27 inches wide, and were sold in white. GE gas dryers model number DWXR463GGWW with serial numbers starting with AM, TL, SL, VL, and ZL are included in this recall. To find the model and serial numbers, open the dryer door and look in the upper right corner, in the area that was covered by the door.	GE Consumer & Industrial, of Louisville, Ky.	September 2006 through October 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08542.html			
Children's Table and Chair	The surface paint on the children's table and chair sets contains excessive levels of lead, violating the federal lead paint standard.	Consumers should immediately take the table and chair set away from children. Netshops is offering consumers a full refund. Netshops has directly contacted consumers who purchased the table and chair sets.	The recalled table and chair sets are natural colored. The table is either round or rectangular, has a shelf under the table and includes two chairs. Model number ALZ024-3 or ALZ023-3 is printed on the packaging.	Netshops, of Omaha, Neb.	November 2007 through December 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08543.html			
Polaris All-Terrain Vehicles (ATVs)	The ATVs can have defective Electronic Control Modules (ECM) that overheat, posing a fire and burn hazard to riders.	Consumers should disconnect the negative (black) battery cable from the battery when the ATV is not in use. Consumers should contact their local Polaris dealer to schedule a free repair. Registered owners received direct mail notification of this recall.	This recall involves select 2005 through 2006 model Polaris Sportsman and Scrambler 500 ATVs. The model and serial numbers are printed on a decal attached to the front side of the radiator (Sportsman) or the top of the front cab cover (Scrambler 500). Serial numbers are permanently stamped into the left frame rail behind the left front wheel.	Polaris Industries Inc., of Medina, Minn.	July 2004 through January 2008	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08193.html			
Wendy Bellissimo Hidden Hills Collection Drop-Side Cribs	Spindles on the drop-side of the crib could loosen creating a gap that poses an entrapment and strangulation hazard.	Consumers should stop using the crib immediately and contact Bassettbaby for a free replacement or a full refund. The firm has contacted consumers directly.	This recall involves a full-size, drop-side crib from the Wendy Bellissimo Hidden Hills collection, model number 5446-0504. The model number is located on the bottom rail of the headboard. The crib was sold in a Navajo Pine finish. No other models are included in this recall.	Bassettbaby, of Bassett, Va.	November 2007 through January 2008	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08544.html			
Louisville/Davids on" and "Michigan" Brand Fiberglass Extension Ladders	The extension or "fly" section can fail to lock, posing a fall hazard to consumers.	Consumers should stop using the ladder immediately and contact Louisville Ladder for instructions on inspecting the ladder and receiving a free repair kit, if necessary.	The recalled ladders are Type I, IA, or II extension ladders with fiberglass rails and "D" shaped aluminum rungs.	Louisville Ladder Inc., of Louisville, Ky.	September 2007 through December 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08197.html			

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
Portable Electric Heaters	The portable electric heater can overheat and melt plastic parts, posing a fire hazard to consumers	Consumers should immediately stop using the recalled heaters and contact Aloha Housewares to receive a replacement product.	This recall involves electric oscillating tower heaters with the name "Aloha Breeze" printed on the top. The white heaters have model number 02044 and dates codes 06/06, 06/07, 06/08 or 06/09. Model numbers and date codes are printed on the silver label located on the back of the heater, near the bottom.	Aloha Housewares Inc., of Arlington, Texas	August 2006 through November 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08198.html			
Indirect Gas-Fired Furnaces	The ignition control module can fail preventing the unit from shutting down in high temperature conditions. This poses a risk of fire, as well as hazardous fumes being released from burning/melting insulation.	Property managers or job sites who have not been contacted by Greenheck Fan should contact the firm to arrange for a free repair.	The recall involves Greenheck Fan Indirect Gas-Fired Furnaces models PVF, PVFH, IGX, IG, ERH and ERCH. The model name is located on the control center door or the furnace door. The furnace is either natural gas or LP gas (propane) fueled. Only units with ignition control module model number 35-615922-125 are included in the recall.	Greenheck Fan Corp., of Schofield, Wis.	November 2006 through October 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08545.html			
Memory Testing Cards (sold as part of educational testing kits)	Surface paint on the cards contains excessive levels of lead, violating the federal lead paint standard.	Purchasers should immediately stop using the recalled memory cards and return them to Riverside Publishing for free replacement cards. The firm is contacting purchasers directly.	The recall involves the Universal Nonverbal Intelligence Test—Symbolic Memory Cards. The memory testing cards are part of a kit used to test children's physical and mental abilities. They are white with green figures, measure 1 ½" x 1 ½", and were sold as part of a kit (model number 922782), or were sold in packages of 10 cards (model number 922775). The model numbers are located on the packaging.	Riverside Publishing Co., of Rolling Meadows, Ill.	January 2003 through November 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08546.html			
Majestic Curved Top and Flat Top Cribs, Essex Cribs, Brighton/Sussex Cribs and Captiva Cribs	The cribs fail to meet the federal safety standards for cribs. The four support brackets on the mattress support spring are too long. The brackets prevent the spring from lowering to the full 26 inch minimum height in its lowest position, allowing children inside to crawl over the railing, posing a fall hazard.	Consumers should stop using the recalled cribs and contact Munire Furniture to receive replacement spring brackets.	The cribs are wooden. The recalled cribs include: Majestic Curved Top cribs with model number 9500; Majestic Flat Top cribs with model number 9000; Essex cribs with model number 7100; Brighton/Sussex cribs with model number 9100 and Captiva cribs with model number 5100. Only cribs with manufacture dates between November 1, 2005 and November 1, 2007 are included in the recall. The crib model number is printed on the white label on the bottom inside of the right side rail. The crib manufacture date is printed on either the white label near the model number or on the white label located on the bottom of the headboard. Cribs with a green sticker on the mattress frame are not included in the recall.	Munire Furniture Inc., of Piscataway, N.J.	November 2005 through November 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08202.html			
Select "Outlaw IRS" ATVs, Model Year 2006-2008	A retention bolt can come loose causing the rear wheels to lock up, which poses a risk of serious injury to the rider. A retention bolt can come loose causing the rear wheels to lock up, which poses a risk of serious injury to the rider.	Consumers should stop using the recalled ATVs immediately, and contact any Polaris ATV dealer to schedule a free repair. Polaris has notified registered consumers directly about this recall.	The recall involves select 2006-2008 Polaris "Outlaw" ATVs with Independent Rear Suspension (IRS). The affected models are: Model 2006 OUTLAW 500 "IRS" 2007 OUTLAW 500 "IRS" 2007 OUTLAW 525 "IRS" 2008 OUTLAW 525 "IRS"	Polaris Industries Inc., of Medina, Minn.	January 2006 through January 2008	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08547.html			

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
LDR 1200 Series Gas Connectors	The gas connectors can leak propane or natural gas, posing a fire and explosion hazard to consumers.	Consumers should immediately stop using the appliance with the recalled gas connectors. Only a qualified professional, such as a plumber, heating contractor or gas company technician, should check the connectors and replace them. Contact LDR Industries or the place of purchase for instructions on returning the connectors for a full refund.	The recalled LDR series 1200 gas connectors have 3/8 inch fine thread nuts attached. The connectors are used primarily with gas space heaters. The brass nuts are gold colored while the stainless steel tube is silver colored. The following connectors are included in this recall. The UPC code and "LDR 1200 Series Gas Connector" are printed on the product's packaging.	LDR Industries Inc., of Chicago, Ill.	August 2007 through September 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08205.html			
Electric Contact Grills	Cooking oils or sprays applied to the grill's cooking plates before preheating can cause the oil to ignite and/or flare up. Cooking sprays can ignite and/or flare up if used on the grill at any time.	Consumers should immediately stop using cooking oils on the grill prior to preheating. Cooking sprays should not be used on the grill at anytime. Consumers will receive a revised instruction manual with a cooking spray/oil use warning. QVC has sent warning notices to consumers to whom it sold the product directly. Tristar will do the same.	This recall involves a dual surface electric contact grill sold under the "Hulk Hogan's Ultimate Grill" brand. The grills are silver/gray in color, have removable cooking plates, a cassette to catch drippings, and fold for storage or transport. Model number PZ-3012 is printed on a silver label attached to the back of the grills.	QVC Inc., of West Chester, Pa., and Tristar Products Inc., of Fairfield, N.J.	May 2007 through August 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08549.html			
Strike Force™ Portable Air Compressors	The compressor's motor can overheat and ignite the protective cover, posing a fire hazard to consumers. Also, the cover might not prevent internal components from being touched, which poses an electrical shock hazard.	Consumers should stop using the air compressor immediately and return it to any Advance Auto Parts store for a full refund.	The recall involves the 4.6 gallon, 3.5 HP Strike Force™ brand portable air compressor and includes the following model and serial numbers: Model Number Serial No. BMM2524 (25254) JWAPC4005xxxxxxxxx AC251FT (2516) YFJAC4005xxxxxxxxx APC4005 (4005) CSCC4005xxxxxxxxx The compressor has twin air tanks that are black-colored. The model and serial numbers are located on the compressor's housing.	Advance Stores Co., d.b.a. Advance Auto Parts, of Roanoke, Va.	October 2006 through December 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08210.html			

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
Hamilton Beach® and Proctor-Silex® Toasters	The toasters can remain "on" (energized) after popping up, and can ignite flammable items covering or in contact with the toaster, posing a fire hazard.	Consumers should immediately stop using the recalled toasters and contact Hamilton Beach for instructions to receive a free replacement toaster.	The recalled Hamilton Beach® and Proctor-Silex® toasters are black, red, white, chrome or brushed chrome with 2-slice or 4-slice openings. Hamilton Beach or Proctor-Silex is printed on the side of the toasters. Only specific series codes of each model are included in this recall. The model number and series code are printed on the bottom of the toasters. Toaster Model Numbers 22145B 22779 22145BC 22900 22450 22903 22559 22903H 22625 24450 22627C 24559 22635 24657 22657 24779 22658	Hamilton Beach Brands Inc., of Glen Allen, Va.	August 2007 through February 2008	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08212.html			
Cooks Deep Fryers	The deep fryer has a faulty heating element which can cause it to overheat, posing a fire and burn hazard to consumers.	Consumers should immediately stop using the deep fryer and return it to the nearest JCPenney store for a full refund	The Cooks deep fryer has a brushed stainless steel exterior, a wire mesh basket with a handle, a lid with a window and black handles. The deep fryer has a 1/3-gallon capacity. "Cooks" is stamped on the side of the deep fryer. Model number 22016 is printed on the bottom of the deep fryer.	JCPenney, of Plano, Texas	August 2007 through January 2008	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08216.html			
Wire-O Bound Journals and Calendars	The paint on the metal spiral bindings of the journals contains excessive levels of lead, which violated the federal lead paint standard.	Consumers should remove the back cover of the calendars/journals with the ISBN barcode number and contact Galison for instructions on returning the back cover for a refund. The journals/calendars should be discarded.	The recalled journals are spiral bound journals, activity books, and calendars sold in a variety of styles, sizes and colors. Galison or Mudpuppy and the ISBN numbers are printed on the back cover of the calendars/journals.	Galison/Mudpuppy, of New York, N.Y.	August 2003 through December 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08226.html			
Electric Toasters	The toaster can turn on without bread in the slots and ignite items placed on top of it, posing a fire hazard.	Consumers should stop using the toaster immediately, unplug it, and cut off the power cord where it enters the body of the toaster. Consumers who return the power cord in the prepaid envelope that will be provided will receive a full refund.	This recall involves the chrome two-slice electric toasters sold under the following brands: Farberware (model # FCT200 or FCT100), Hoffritz (model # HZT2 and HZT2M), and Russell Hobbs (model #RH2MT). The brand name and model number are printed on a plate located on the underside of the toaster.	Salton Inc., of Lake Forest, Ill.	January 2000 through December 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08227.html			

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Present</u>	<u>Not Present</u>	<u>Abated</u>
Progress Lighting Outdoor Ceiling Light Fixtures	A weld that affixes a mounting bracket to the ceiling pan can fail, which can cause the fixture to fall and injure nearby persons.	Consumers should contact Progress Lighting to schedule a free repair of the lighting fixture.	Only Progress Lighting ceiling-mounted outdoor light fixtures with model numbers P5526-20 and P5526-44 are included in the recall. The light fixtures have three flame-shaped lights inside a beveled glass and solid frame. The fixtures require (3) 60-watt light bulbs. "Made in/Hecho En/Fabrique Aux China" and the model numbers are written on the packaging of the product.	Progress Lighting, of Greenville, S.C.	January 2007 through November 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08228.html			
Model Year 2008 Rhino YXR450 and YXR700 Side-by-Side Vehicles	The brake caliper on the left front wheel could have been made incorrectly, resulting in brake fluid leaking. This can cause a loss of braking and control of the vehicle, posing a serious safety risk to the driver and passenger.	Consumers should immediately stop using the recalled Rhinos and contact any authorized Yamaha Rhino dealer to schedule a free repair. Registered owners were sent direct mail notification of this recall.	This recall involves model year 2008 Rhino YXR450 and YXR700 Side-by-Side Vehicles	Yamaha Motor Corporation U.S.A., of Cypress, Calif.	October 2007 through March 2008	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08552.html			
Ring Toss Games	The paint on the yellow peg of the toy contains excessive levels of lead, violating the federal lead paint standard.	All purchasers have been contacted and requested to return the games for a store credit or refund.	The recalled ring toss game has three plastic blue rings and five 4-inch wooden pegs. Four of the five pegs are purple and one is yellow. The base of the game is made of two red wooden boards that form an "X" when assembled.	Educational Insights, of Vernon Hills, Ill.	December 2007 through February 2008	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08553.html			
Cozy Warming Polar Bears	The warming pouch inside the bear can overheat and ignite when heated in a microwave oven, posing a fire and burn hazard to consumers.	Consumers should immediately stop using the recalled warming bear and return the buckwheat-filled pouch for a full refund. Avon is directly contacting consumers who purchased the warming bear.	The recalled white plush warming bear has a red hat and brown nose. It is about 17 inches long and comes with a buckwheat-filled pouch that is heated in a microwave oven and is inserted into an opening in the bear's belly. "Avon Products" is printed on a white tag sewn onto the bear.	Avon Products Inc., of New York, N.Y.	July 2007 through February 2008	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08554.html			