

Dangerous and Recalled Products - Transmittal Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
Ohalee FA-A70 Youth ATVs	These youth ATVs lack front brakes and a tire pressure gauge, the date of manufacture is not printed on side of the tires, and the front suspension is solid and does not allow for travel. Additionally, the flag pole bracket is not the correct size, and the handlebars do not have padding covering sharp edges. There is no storage location for the owner's manual, and the manual itself does not contain complete information on the safe operation and maintenance of the ATV. These defects could result in an unsafe riding condition, posing a risk of injury to young drivers.	Consumers should immediately stop using the ATVs and contact the retailer for a full refund. Ohalee, Inc. will contact the consumers and notify them the full refund policy.	This recall involves the Ohalee FA-A70 Youth ATVs, which has the name "Ohalee" on the right and left side of each ATV. The 70cc size ATVs were available in the following colors: red, blue, and black.	Odes Motorcycle Industry nationwide	June 2006 through December 2006	http://www.cpsc.gov/cpscpub/prerele/prhtml07/07576.html			
Cook's Essentials Convection Ovens with Pull-Out Rotisserie and Deni Convection Ovens with Rotisserie	Wires behind the control panel can overheat, posing fire and electric shock hazards.	Consumers should immediately stop using the oven and contact QVC or Keystone to receive a replacement oven or a refund. QVC and Keystone have notified consumers by telephone and by mail to stop using the oven.	This recall involves the Cook's Essentials Multi-Function Convection Oven with Pull-Out Rotisserie (model number 910500), which was also sold as the Deni Convection Oven with Rotisserie (model number 10500). The model number can be found on the bottom of the oven. These are countertop ovens and the brand name "Cook's Essentials" or "Deni" is found on the front right panel.	The Cook's Essentials brand was sold exclusively through QVC and the Deni brand was sold through various on-line retailers	October 2006 through May 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml07/07577.html			
IT400 Iced Tea Makers	The iced tea maker's components can fail, posing a fire hazard to consumers.	Consumers should stop using and unplug the recalled iced tea makers immediately and contact Back to Basics Products to receive a free replacement product or refund.	The recalled Iced Tea Maker (Model #IT400) is mostly white and has a 2.5 quart glass pitcher. The recall includes only those products with a date code of CA1307 or CA1307-A. The model number is embossed on the bottom of the unit, and the date code is printed on a small white sticker, which is also on the bottom of the unit.	Bon-Ton department stores and hardware stores nationwide, the JCPenney catalog, and Internet retailers	April 2007 through July 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml07/07306.html			
Single Post Swing Sets	The connection on the top beam of the swing set can break, causing the swing beam to collapse, posing a fall hazard to the user. A user or bystander also can be injured by the falling top rail.	Consumers should stop using the product immediately and remove the existing swings from the top beam immediately. Consumers can re-install the swings once the repair kit is received and installed with the current beam. BCI Burke will contact the owners directly by mail and provide a free repair kit.	The recall includes the Single Post Swing Set (model 550-0033) and added bay swings (model 550-0035) with belt or bucket seats. The swings are made with a 2-3/8-inch diameter top beam that is welded to a formed plate on each end to attach to the upright post.	BCI Burke or BCI Burke Company representatives	January 2000 through August 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml07/07579.html			
TOBY & ME Jewelry Sets	The recalled metal jewelry sets contain high levels of lead. Lead is toxic if ingested by young children and can cause adverse health effects.	Consumers should immediately take the recalled jewelry away from children and contact TOBY N.Y.C. for information on receiving a full refund or replacement item.	This recall involves jewelry sets sold in different styles: a pink and clear crystal bead necklace and bracelet set with a painted metallic crown pendant; a pink and white pearl necklace and bracelet set with a painted metallic poodle pendant; and a pink pearl necklace, earrings and ring set. This recall is expanded to include two additional styles: a pink crystal and wood bead necklace and bracelet set with a monkey pendant; and a pink and clear crystal bead necklace and bracelet set with a heart pendant. All sets are sold in a pink gift box with "TOBY & ME" printed on the front and "TOBY & ME" hangtags attached to the packaging.	T.J. Maxx, Marshalls, A.J. Wright, Cracker Barrel, and Shopko stores nationwide	August 2006 through August 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml07/07314.html			

Dangerous and Recalled Products - Transmittal Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
Floor Puppet Theaters	Surface paints on the puppet theater's wooden panels contain excessive levels of lead, violating the federal lead paint standard.	Consumers should immediately take the recalled puppet theaters away from children and contact Guidecraft to receive a replacement theater or another product of equal value.	The recalled puppet theater has a chalkboard surface on the front and colored side panels. The puppet theater measures about 35 inches in length, 14 inches in width and about 52 inches in height.	Specialty toy stores, gift shops, catalogs and Web sites nationwide	June 2006 through August 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml07/07312.html			
Happy Giddy Gardening Tools and Children's Sunny Patch Chairs	The surface paint on the recalled gardening tools and chairs contains excessive levels of lead, violating the federal lead paint standard.	Consumers should immediately take the products away from children and return the item to the nearest Target store for a full refund.	The recall includes the Happy Giddy Gardening Tools and the Sunny Patch Children's Chairs. Gardening tools: caterpillar trowel with an orange and multi-colored handle; kitty cat broom with pink flowers and green handle; pink and green cultivator with a solid green tool portion and pink flowers on the handle; orange and green wood handle hoe and rake with orange flowers; pink and green shovel and trowel with pink flowers; green, orange and light blue snail push broom; multi-colored trowel, hoe, rake with orange on the tool body; multi-colored shovel with solid red on the shovel and eyes on the top of the handle; red and blue owl shaped broom with bristles painted blue, with yellow and black large eyes on the face. Children's Chairs: multi-colored children's Sunny Patch chairs with a giraffe, monkey, and elephant on the back. The cloth seat and back are striped in orange, yellow, green and blue. The chameleon, butterfly and lady bug chair are not included in the recall.	Target stores nationwide	August 2006 through August 2007				
Cook's Essentials Electric Toasters	The toaster can turn on without bread in the slots and ignite items placed on top of it, posing a fire hazard.	Consumers should stop using the toaster immediately, unplug it, and cut off the power cord where it enters the body of the toaster. Consumers who return the power cord in the prepaid envelope that will be provided will receive a full refund.	This recall involves the "Cook's Essentials" four-slice wide slot electric toasters model CET 401. These toasters are made of stainless steel and measure 12 inches long, 13 inches wide and 8 inches high. Each toaster has "Cook's Essentials Classic Look Toaster, Model: CET401" printed on a plate located on the underside of the toaster.	QVC through its television station, its Web page; its toll-free number, outlet, and its employee and Studio stores. Some recalled toasters may have been sold at various retailers.	January 2003 through June 2003	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08001.html			
Timberland PRO Direct Attach Steel Toe Boots	The boots could fail to provide the intended protection against compression and impact, posing the risk of a foot injury to consumers.	Consumers should stop wearing the recalled boots immediately and contact The Timberland Company to receive a free replacement pair of boots.	This recall involves the Timberland PRO Direct Attach Steel Toe Boots with model numbers 26002 (wheat nubuck leather), 65016 (wheat nubuck leather), 26038 (black full-grain leather), and 38021 (brown oiled full-grain leather). The model number is printed on a green loop tag on the inside of the boot, just below the size. The boots have a four digit date code ending in 35 and beginning with the numbers 25 through 45 (e.g. 2535, 2635...4535) which can also be found on the loop tag below the model number. Direct Attach Steel Toe boots made in China are not subject to this recall.	Shoe stores and other independent retailers nationwide	September 2005 through September 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08500.html			

Dangerous and Recalled Products - Transmittal Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
Bookmarks and Journals	Paint on the spiral metal bindings of the journals, clip of the bookmarks and the clear coating on the marquis bookmarks and bracelets contain excessive levels of lead, which violates the federal lead paint ban.	Consumers should immediately take the bookmarks and journals away from children and contact Antioch Publishing for a refund.	<p>This recall involves various designs of bookmarks and journals from Antioch Publishing's Signature Collection. The character-themed bookmarks and journals include the following designs:</p> <p>Clip Bookmarks Winnie the Pooh (© Disney) Lady Bug & Flower Hope & Courage Star Sun & Rainbow Sun & Moon Coffee Follow Him & Cross Monkey & Bananas</p> <p>Marquis Bookmarks Dragon Hugging Cat</p> <p>Bookmarks Sold with Bracelets Mother's Touch Breast Cancer</p> <p>Journals Cherry Blossoms Sweetheart Sassy</p>	Book, card and gift stores nationwide	March 2005 through October 2007	http://www.cpsc.gov/cpsc/pub/prerele/prhtml08/08010.html			
Key Chains	The key chains contain high levels of lead. Lead is toxic if ingested by young children and can cause adverse health effects.	Consumers should immediately take these key chains away from young children and return them to the store where purchased for a refund or replacement product.	This recall involves key chains with a coiled cord and a metal charm with one of the following engraved words: "wisdom", "truth", "believe", "love", "hope", or "dream". The key chains were sold on a cardboard tab with floral designs and the words "Metal Keyring" and "\$1" on the front.	Dollar General stores nationwide	June 2005 through August 2007	http://www.cpsc.gov/cpsc/pub/prerele/prhtml08/08009.html			
Wooden Pull-Along Alphabet & Math Blocks Wagons, Wooden Pull-Along Learning Blocks Wagons, 10-in-1 Activity Learning Carts, and Flip-Flop Alphabet Blocks	Surface paints on the toys can contain excessive levels of lead, violating the federal lead paint standard.	Consumers should immediately take the recalled toys away from children and return them to any KB Toys retail store for a store credit.	<p>The recalled wooden toy wagons have 28 blocks and a pull string. The wagons measure about 7½" x 13" and have blocks with letters, words, numbers, or pictures on them. "First Learning" or "My Kidz" are printed on the products' packaging, in addition to UPC #834162002158 or #834162002165.</p> <p>10-in-1 Activity Learning Carts: The recalled activity carts are three dimensional learning toys with various activities. The cart measures about 17¼" x 16½" x 7¾". "First Learning" and UPC #834162002127 are printed on the product. The recalled wooden toys have blocks that flip with letters, words, numbers, and pictures on them. The toy measures about 10 1/8" x 10¾" x 2¾". "First Learning" and UPC #834162001212 are printed on the products' packaging.</p>	KB Toys stores nationwide.	The Pull-Along Wagons were sold from August 2005 to August 2007, the 10-in-1 Activity Learning Carts were sold from August 2006 to September 2007, and the Flip-Flop Alphabet Blocks were sold from August 2006 to September 2007	http://www.cpsc.gov/cpsc/pub/prerele/prhtml08/08004.html			
IonizAir™ Table Top Air Purifiers	The air purifier's cartridge can overheat, posing a risk of fire.	Consumers should stop using and unplug the recalled air purifier immediately, and contact the firm for a free replacement cartridge.	The recalled air purifier is a tabletop model that is about 6" x 3 1/2" x 11 1/4". The unit has a removable cartridge with a silver-colored handle. The recall involves model number P4620 with lot numbers beginning with either 03 or 04 or having no lot number. The lot number is located on the bottom of the air purifier. No other models or lot numbers are included in this recall.	Various retailers nationwide including mail-order and Internet retailers	January 2003 through July 2004	http://www.cpsc.gov/cpsc/pub/prerele/prhtml08/08012.html			

Dangerous and Recalled Products - Transmittal Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
Cub Scouts Totem Badges	The surface paints on the badges contain excessive levels of lead, violating the federal lead paint standard.	Parents should immediately remove the badges from clothing and keep the badges away from children. Contact the firm for instructions on obtaining a free replacement badge.	The recalled Cub Scout Totem Badges measure 4½ inches x 3 inches with a square portion measuring 2¼ inches x 2¼ inches. The Boy Scout emblem is printed on the badge along with a wolf and bear. "PROGRESS TOWARD RANKS" is also printed on the badge.	Boy Scouts of America retail outlets nationwide	January 2000 through September 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08018.html			
Lithonia Lighting Nickel End Wrap Fluorescent Ceiling Light Fixtures	A wire inside the light fixture could be loose, posing an electrical shock hazard to consumers.	Consumers should stop using the light fixture immediately and return the product to Home Depot to receive a full refund or free replacement. Before removing the fixture, consumers should turn off the power at the home's circuit breaker and consult the installation instructions provided with the fixture. For a complete set of instructions, visit the firm's Web site at www.Lithonia.com	The recall involves the Lithonia Lighting Nickel End Wrap fluorescent ceiling light fixtures model number "New 2 32 120 RE BN" and date code "N050807". The light fixtures measure four feet long and consist of two brushed nickel end caps and a clear plastic cover for the fluorescent tubes. "Lithonia Lighting", the model number, and the date code can be found on the shipping box or on a label located inside the fixture, next to the fluorescent tube. To read the label on the fixture, consumers should turn the power off at the home's circuit breaker and remove the plastic cover of the light fixture. Light fixtures sold in a box marked with a round pink sticker are not included in this recall.	Exclusively at Home Depot stores	June 2007 through August 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08016.html			
Toshiba AC Adapters Sold with Portable DVD Players	The AC adapters can fail, causing the portable DVD player to overheat, posing a burn hazard to consumers.	Consumers should stop using the AC adapters immediately and contact Toshiba Customer Solutions for a replacement adapter.	This recall involves the AC adapter sold with the Toshiba portable DVD player Model SD-P1600. "Toshiba" and ADPV16 can be found on the side of the adapter. "Toshiba", Model SD-P1600, and the serial number can be found on a rating label on the bottom of the cabinet for the DVD player.	Consumer electronics stores nationwide	January 2005 through April 2006	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08015.html			
Deluxe Wood Art Sets	Surface paint on the outside of the wooden box contains excessive levels of lead, violating the federal lead paint standard.	Consumers should take the recalled products away from young children immediately and return it to any J.C. Penney store for a full refund.	The recalled art set consists of a wooden box with several pull-out trays containing 177 different art items, including paints and brushes.	The J.C. Penney catalog and Web site	September 2005 through August 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08023.html			
Kidnastics Balance Beams	Surface paint on the balance beam contains excessive levels of lead, violating the federal lead paint standard.	Consumers should immediately stop using the beam and contact Flaghouse for a free replacement, a full refund, or credit toward the purchase of another product.	The recall involves a foam balance beam measuring 72-inches x 4-inches x 1/2-inch with a blue vinyl cover. A yellow Kidnastics logo is printed on the top of the beam.	Various catalogs and Internet Web sites	January 2007 through September 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08501.html			
Alyssa" Shag Rugs	The rugs fail to meet federal standards for flammability and could ignite, posing a risk of fire and burn injuries to consumers.	Consumers should stop using the recalled rugs immediately and return the rugs to any J.C. Penney store for a full refund.	This recall involves "Alyssa" shag rugs that were available in the following dimensions: 2' x 3' oval, 4' x 6' oval, 5' x 8' oval, 8' x 11' oval, 8' round, and a 2' x 6' rectangular runner. The rugs have a one-inch pile height and were available in four color patterns: red/natural/brown, chocolate/olive/natural, gold/rust/natural, and blue/rust/green/natural.	The J.C. Penney catalog and Web site	June 2007 through August 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08025.html			

Recalled and Recalled Products - Transmittal Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
Model HSR natural gas regulators and various models of LP-gas regulators	Gas can leak from regulator's flanges when flange screw heads break, posing a fire or explosion hazard to consumers.	Consumers who had a natural gas or LP-gas system installed with a recalled regulator should immediately contact the company that provides their natural gas or LP-gas services to receive a replacement regulator installed free-of-charge.	The recalled gas regulators were manufactured from March 2007 through May 2007 and installed on natural gas or LP-gas supply systems in homes and small commercial buildings. The recalls involves model HSR natural gas regulators and LP-gas regulators with model numbers 67CD, 67CH, 67CN, and 67CW, HSRL, R622, R622E, R622H, R632, R642, R652, R652E, R122H, R222, or R232. The model number can be found on a white label attached to the regulator spring case. The date of manufacture is also stamped on the regulator.	FCI to gas supply system dealers and utilities nationwide	March 2007 through June 2007.	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08502.html			
Rocky Mountain Solo Bicycles	The head tube can detach from the rest of the frame, posing a fall hazard to consumers.	Consumers should stop using the bicycle immediately and return the frame to the bicycle store where purchased to receive a free replacement frame, a full refund, or credit.	This recall involves the Rocky Mountain Bicycles brand of Solo bicycles. The models included in this recall are: 2006 SOLO CR50, 2006 SOLO CR70, and 2007 SOLO CR LTD. The bicycles have a full carbon Columbus frame. "Rocky Mountain" and "Solo" are printed on the head tube.	Independent bicycle dealers nationwide	August 2006 through July 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08506.html			
2007 Huffly "Howler" and "Highland" Bicycles	The bicycle crank can unexpectedly come off, causing the rider to lose control, fall and suffer serious injuries.	Consumers should stop using the recalled bicycles immediately and contact Huffly Corp. to receive instructions on tightening the crank.	The recall involves 2007 model year, multi-speed bicycles with 26-inch, 24-inch or 20-inch wheels. The "Howler" was sold in black (model K3587, boy's model), blue (model K4587, men's model), and red (model K6587, men's model). The "Highland" was sold in white (model K4597, women's model) and blue (model K6597, women's model). The name "Howler" or "Highland" is printed on the frame of the bicycle, and the name "Huffly" is on the front of the frame. Model numbers are located on a label on the bottom of the frame where the crank is attached to the bicycle.	Kmart stores nationwide	May 2007 through July 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08028.html			
Cool Clip™ and Mini Cool Clip™ Bookmarks	Paint on the clip of the bookmarks contains excessive levels of lead, which violates the federal lead paint standard.	Consumers should immediately take the bookmarks away from children and contact Antioch Publishing for a refund.	This recall involves various designs of the Cool Clip and Mini Cool Clip bookmarks. The themed metals bookmarks include the following designs: Cool Clips™ Bookmarks Sun (two styles) Daisy/Believe Tiki Flip Flop Lady Bug Music Symbol SHH! Mini Cool Clips™ Bookmarks Flower & Tiki Peace Flower & Yin Yang Lighthouse & Sailboat	Book, card and gift stores nationwide	April 2003 through October 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08032.html			
Tabletop Puppet Theaters	Surface paints on the puppet theater's wooden panels contain excessive levels of lead, violating the federal lead paint standard.	Consumers should immediately take the recalled puppet theaters away from children and contact Guidecraft to receive a replacement theater or another product of equal value.	The recalled puppet theater has red panels on the front and sides and a chalkboard signboard on top. The puppet theater measures about 24-inches in length, 6-inches in width and about 28-inches in height.	Specialty toy stores, gift shops, catalogs and Web sites nationwide	June 2006 through August 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08031.html			

Dangerous and Recalled Products - Recall Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
John Deere Gator Utility Vehicles	The brake calipers in the front of the utility vehicles may have been installed incorrectly, causing the vehicle to pull to one side during braking. This poses an injury hazard to consumers.	Consumers should stop operating the recalled utility vehicles immediately and contact an authorized John Deere dealer in their area to schedule a free inspection. The company will provide free repair, if needed. Registered owners were sent direct mail notification of this recall.	This recall involves the XUV and HPX Gator utility vehicles made by John Deere with model and serial numbers included below. These are four-wheeled vehicles with a cargo box. "John Deere", "Gator", "HPX" and "XUV" are printed on the side of the cargo box. The following model and serial numbers can be found on the serial number plate on the frame of the vehicle. Model XUV 620i Gas Serial Number MOXUVGX013294-016669 Model XUV 620i Gas Serial Number MOXUVGT011480-012186 Model XUV 850D Diesel Serial Number MOXUVDX011917-013329 Model XUV 850D Diesel Serial Number MOXUVDT010001-010449 Model HPX 4X4 Diesel Serial Number MOHP4DX050877-051453 Model HPX 4X4 Gas Serial Number MOHP4GX051221-052763	John Deere dealers nationwide	June 2007 through September 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08509.html			
Inflator Air Pumps (sold separately and included with "Launch Pod" Water Trampolines)	The air pumps can overheat and explode during use, posing a risk of lacerations.	Consumers should immediately stop using the pumps and contact Sportsstuff for a free replacement.	The recalled products are air pumps with model numbers 57-1504 A and 57-1504 that are used to inflate low pressure inflatable items such as rafts and toys. The Model 57-1504-A pump was sold separately with an assortment of interlocking nozzles. The Model 57-1504 pump was sold with the Sportsstuff "Launch Pod", an inflatable water trampoline. The model number and the date code "0104" are located on the label on the top of the pump. Launch Pod water trampolines that included recalled pumps .	Sam's Club	January 2004 through August 2004	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08036.html			
Power Packs for Portable Team Hydration Units	Charging the battery inside the hydration unit's power pack box can result in excessive gas buildup which can burst the lid of the power pack box off or rupture the box. This poses an injury hazard to bystanders.	Consumers should immediately stop charging the portable team hydration units and contact Collegiate Pacific to receive a repair kit.	This recall involves the battery operated power pack boxes for the 20-gallon "Sports Cool Powered Team Drinker" and the 40-gallon "Sports Cool Powered Tanker with Cart" portable team hydration units. The units include a water tank, six hoses, a battery operated pack box, and a cart. "Sports Cool" is printed on the water tank.	Sporting goods supply distributors and direct sales nationwide	February 2004 through June 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08511.html			
All-Terrain Vehicles (ATVs)	The rear brake caliper support can crack; this could result in the potential for a loss of the use of the rear brake and subsequently lead to an accident.	Consumers should stop using these vehicles immediately and contact their local KTM dealer to schedule an appointment for a free repair. Consumers with the recalled ATVs have been sent via U.S. mail a safety recall notice from KTM on September 4, 2007.	This recall involves KTM model year 2008 450XC and 525XC ATVs. The ATV's are orange and black in color and have 450XC and 525 XC branded on the side as well as the KTM™ logo.	KTM dealers nationwide	August 2007 through September 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08510.html			
Cybox or Trotter Treadmills	During repairs associated with the October 8, 2003 recall, wire nuts were installed improperly, causing the treadmills to overheat and posing a fire hazard to consumers.	Consumers whose treadmills were included in the 2003 recall and were repaired should immediately unplug and stop using the treadmills. Consumers with recalled units will be notified directly by Cybex. Consumers should call Cybex directly to schedule a free repair.	This recall involves the treadmills "Cybex 400T," "Cybex 410T," "Trotter 510," "Trotter 525", "Trotter 535", and "CXT+" that were recalled (link) on October 8, 2003 and later repaired. The treadmills are black with gray coloring, have rectangular uprights, and measure 69 inches long and 30 inches wide. The brands and models are written on the display panel. The "CXT+" model does not bear the brand Cybex or Trotter.	Cybex International and Cybex dealers nationwide	September 1993 through October 2001	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08041.html			

Dangerous and Recalled Products - Transmittal Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
Reynolds UL Bicycle Forks	The fork tips could separate from the fork legs, causing the wheel to come loose from the fork while riding. This could pose a serious fall hazard to riders.	Consumers should stop using the bicycles equipped with the recalled forks immediately and contact Reynolds for a free replacement fork.	This recall involves the Reynolds UL bicycle fork models with 43 mm and 50 mm rakes and with serial numbers 09100 through 10403. The serial number decal is located on the steer tube. To see the serial number, the fork must be removed from the frame. Some recalled forks are black, have "Reynolds" printed on them, and have a gray and white stripe painted on the legs of the fork. Other recalled forks were painted with a different paint scheme and do not have "Reynolds" printed on them. To determine if a fork is included in this recall, consumers should contact the company. The recalled forks were included in custom 2007 bicycle frame kits from the following manufacturers: Independent Fabrication, Litespeed, Lynskey Performance Designs LLC., Merlin, Parlee, Rock Lobster, Spectrum Cycles, Strong Frames and Vicious Cycles.	Independent bicycle retailers nationwide	October 2006 through May 2007				
Blastrac BG 250 Series Concrete Grinders with round flexible couplers	The flexible coupler on the concrete grinder can break during use allowing the internal parts, including the tooling plate and grinding disc, to be forcefully ejected from the grinder. This can pose a risk of injury from projectiles to the user and those nearby.	Renters should stop using the product immediately and return it to the rental company. Blastrac has directly contacted owners of these products. Product owners who have not received notice from Blastrac should contact the firm for a free repair kit.	The recalled gas or electric grinders are used to grind concrete surfaces for repair or removal. The grinders have two wheels, a handle and are blue or green in color. They are designed for operation by a single operator. The following concrete grinders are included in this recall. The serial number is located on a plate on the machine's handle. Blastrac Series BG 250 Concrete Grinders Gas-Powered and Electric-Powered	Independent distributors nationwide who sell to professional users, and to equipment rental firms that rent to professional contractors and consumers	November 2006 through July 2007	http://www.cpsc.gov/cpsc/pub/prere/prhtml08/08514.html			
Battery Chargers supplied with certain Kawasaki branded Power Tool Kits	When used with an incompatible charger, the battery pack can overheat and melt during charging, or can explode during use, posing burn, laceration and bruise hazards to consumers.	Consumers should stop using the recalled battery chargers immediately and register at www.alltradetools.com to receive a free compatible battery charger. Alltrade Tools LLC is directly contacting consumers who purchased the power tools containing the recalled chargers. Consumers should not return the battery chargers to the store where purchased.	The recall includes battery chargers sold with certain model numbers of both 19.2 and 21.6 volt NiCad battery packs. The battery model number is located on a label on the bottom of the battery pack. The power tool's model number is stamped onto the inside lid of the tool set's plastic carrying case. KW Black 19.2V Cordless Drill Power Tool Model 840128 Battery Pack Model 691034 KW Black 19.2V 26 PC Drill Set Power Tool Model 840135 Battery Pack Model 691034 KW Black 4 PC Power Tool Combo Power Tool Model 840338 Battery Pack Model 691034 KW Black 2 PC Power Tool Combo Power Tool Model 840339 Battery Pack Model 691034 KW Black 19.2V 26 PC Drill Set Power Tool Model 840135A Battery Pack Model 691240 KW Black 21.6V Cordless Drill Power Tool Model 840266 Battery Pack Model 691221 KW Black 21.6V Cordless Drill Power Tool Model 840267 Battery Pack Model 691221	National wholesale club retailers nationwide	September 2005 through September 2007	http://www.cpsc.gov/cpsc/pub/prere/prhtml08/08513.html			
Counterfeit "Square D" Circuit Breakers	The recalled circuit breakers labeled "Square D" are counterfeit and could fail to trip when they are required to, posing a fire hazard to consumers.	Consumers should contact Connecticut Electric to determine if the breaker they have is counterfeit and if necessary, to arrange for a free inspection and replacement or refund.	The counterfeit circuit breakers are black and are marked as Square D products. Connecticut Electric has identified the following breakers as possibly being counterfeit: QO115, QO120, QO140, QO2125, QO215, QO220, QO230, QO240, QO250, QO260, QO1515, QO2020, QO3100, QO320, QO330, QO340, QO360, QOB120, QOB130, QOB220, QOB230, QOB250, QOB330, and QOB360. Actual Square D circuit breakers have (a) the amp rating written on the handle in white paint on the front of the breaker; (b) the Square D insignia molded onto the breaker side, and; (c) a yellow chromate mounting clip with half of the top of the clip visible. If your Square D breaker does not match this description, it could be counterfeit.	Electrical Distributors and hardware stores nationwide	February 2005 through August 2006	http://www.cpsc.gov/cpsc/pub/prere/prhtml08/08054.html			

Quarterly and Recalled Products - Transmittal Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
C9600 Series Digital Color Printers	The recalled digital color printers have an internal electrical problem that could result in electrical shock to consumers.	Consumers should immediately stop using the recalled printer. Do not touch the printer or attempt to turn it off. Unplug the printer immediately by pulling the plug from the wall socket. Unplug the printer before locating the serial number on the back of the unit. Contact the firm for a free inspection and repair.	The digital color printers are beige colored and measure 27 inches wide, 25 inches deep and 20 inches high. "OKi Printing Solutions" and model "C9600" are printed on the front of the unit. The following serial numbers are included in the recall. The serial number is located on the back left side of the printer. Serial Numbers AA56002655A0 through AA56002804A0 AA58001468A0 through AA58001617A0 AA58002702A0 through AA58002801A0	Authorized OKI Printing Solutions Dealers and Solution Providers nationwide	August 2005 through September 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08052.html			
Rabbit Board Games	Surface paint on the five frog-shaped wooden pieces contain excess levels of lead, violating the federal lead paint standard.	Consumers should immediately remove the five frog pieces from the game and discontinue using them. Consumers should contact SimplyFun for a refund or a set of five replacement frogs.	This recall involves SimplyFun Rabbit board games. The games are sold with five frog-shaped wooden pieces that act as pawns for movement. The wooden pieces are blue, red, green, yellow and lavender in color.	SimplyFun independent consultants nationwide	March 2007 through October 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08056.html			
Warm Mist Carefree Humidifier	Water used in the humidifier can leak into the unit's electrical compartment, posing a fire hazard.	Consumers should immediately stop using and unplug the recalled humidifiers. Consumers should contact Hunter Fan to receive a free replacement humidifier or refund.	This recall involves Warm Mist CareFree humidifiers sold in white and black with blue or green tinted water tanks. "Hunter" and "NiteGlo" are printed on the humidifier. Model numbers are listed on a white label on the bottom of the humidifier. Model numbers and tank sizes are listed in the chart below. Model Number 36200 Carefree® Humidifier Warm Mist 2 Gallon White plastic with a blue tinted water tank Model Numbers 35201, 36201 Carefree® Humidifier Warm Mist 2 Gallon White plastic with a blue tinted water tank Model Numbers 35202, 36204 CareFree® Humidifier Warm Mist 2 Gallon White plastic with a blue tinted water tank Model Numbers 35203, 36203, 37203 CareFree® Humidifier Warm Mist 2 Gallon White plastic with a green tinted water tank Model Numbers 35207, 36207 CareFree® Humidifier Warm Mist 2 Gallon White plastic with a blue tinted water tank Model Numbers 35253, 36253 CareFree® Humidifier Warm Mist 2.5 Gallon Black plastic with a blue tinted water tank	Lowe's, Wal-Mart, discount and hardware stores nationwide, as well as through mail order catalogs and Web retailers	September 2005 through February 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08064.html			
Packaged Terminal Air Conditioners (PTAC) and Heat Pumps (PTHP)	An electric heater in the unit can break, posing a fire hazard to consumers.	Consumers should stop using the heating mode of the recalled units until they are inspected in accordance with Carrier's inspection instructions, which can be found at www.carrierptacrecall.com . Consumers should contact Carrier to receive a free repair.	This recall involves Carrier-brand packaged terminal air conditioners (PTAC) and packaged terminal heat pumps (PTHP) manufactured between 2002 and 2005. Model numbers included in the recall are 52C, 52P, and unbranded model 84 units sold through the Bryant and FAST channels. Serial and model numbers are located on the rating/data plate on the right front of the unit, underneath the removable front panel. A complete list of the serial numbers involved in this recall can be found at www.carrierptacrecall.com . The units were sold with 208/230 and 265 volts, and have capacities of 7,000, 9,000, 12,000, and 15,000 BTUs.	HVAC dealers and factory-direct sales	January 2002 through December 2006	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08073.html			
"Big Red" Wagons	Surface paints on the wagon and handle contain excessive levels of lead, violating the federal lead paint standard.	Customers should immediately take the recalled wagon away from children and return it to any Northern Tool store for a free replacement.	The recalled wagon has a red painted, steel deck with removable wooden sides. The wheels have ball bearings and air-filled tires.	Northern Tool & Equipment catalog, Web site, and retail stores nationwide	July 2007 through September 2007	http://www.cpsc.gov/cpscpub/prerele/prhtml08/08066.html			

Dangerous and Recalled Products - Transmittal Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
Curious George Plush Dolls	Surface paint on the toy's plastic face and construction hat contain excessive levels of lead, which violates the federal lead paint standard.	Consumers should immediately take the recalled toys away from children and contact Marvel Toys to receive a full refund.	This recall involves Curious George 12-inch plush dolls with a plastic face. The dolls are dressed to represent five various themes: birthday, fireman, sweet dreams, tool time and tool time with a soft face. The plush dolls were sold with a Curious George storybook or activity book. The following product and SKU numbers are printed on the packaging. Birthday 90253/ 8-83199-90253-5 Fireman 90246/ 8-83199-90246-7 Sweet Dreams 90247/ 8-83199-90247-4 Tool Time 90251/ 8-83199-90251-1 Tool Time (soft face) 90251/ 8-83199-90251-1	Toy and discount department stores nationwide	December 2005 through August 2007	http://www.cpsc.gov/cpsc/pub/prerelease/prhtml08/08079.html			
Yamaha AC Power Adaptors	The housing of the power adaptor can separate, posing an electric shock hazard to consumers.	Consumers should stop using the recalled power adaptor immediately and contact Yamaha to return the power adaptor and obtain a free replacement.	This recall involves the Yamaha PA-3C power adaptor with a date code of 0624. The adaptor is used with Yamaha keyboards and digital drum sets. The model number is written in white print on the front of the plug of the adaptor and the date code is etched into the plastic at the bottom of the plug panel. The adaptor can be purchased as part of a set or separately.	Musical instrument retailers nationwide	July 2006 through September 2007	http://www.cpsc.gov/cpsc/pub/prerelease/prhtml08/08078.html			
Honda HRX217KHXA and HRX217KHMA Lawn Mowers	Due to a manufacturing defect, a crack can occur in the fuel tank causing a fuel leak. If gasoline leaking from the fuel tank is ignited, a fire or explosion can occur.	Consumers should stop using these recalled lawn mowers immediately and contact any Honda Lawn and Garden dealer to have the fuel tank replaced. Registered owners of the recalled lawn mowers will be mailed a notice.	The recall involves HRX walk-behind lawn mowers with model numbers HRX217KHXA and HRX217KHMA. Only serial numbers from 1400001 through 1453714 are included in the recall. The model and serial number are printed on a label located on the upper rear of the deck. The lawn mower is dark gray with a red engine cover.	Honda Lawn and Garden dealers nationwide, including The Home Depot stores	January 2007 through September 2007	http://www.cpsc.gov/cpsc/pub/prerelease/prhtml08/08077.html			
Plastic Folding Chairs	The plastic folding chairs can collapse during use, posing a fall hazard to consumers.	Consumers should stop using the chairs immediately and contact Iceberg Enterprises to receive a free repair kit with instructions.	This recall involves Iceberg plastic round leg folding chairs. The metal support of the chair is charcoal and the seat and back support are beige. "Iceberg" is printed on a logo located on the back of the seat. Chairs with oval-shaped legs are not included in this recall.	Office supply retailers nationwide	August 2005 through July 2007	http://www.cpsc.gov/cpsc/pub/prerelease/prhtml08/08082.html			
Football Helmet Chin Straps	The chin strap's plastic cup can break as a result of contact, exposing the player to facial or head injuries.	Consumers should stop using the chin strap immediately and contact Nike for a product voucher redeemable at www.nikestore.com	The recalled football helmet chin strap consists of a plastic cup with a foam liner, straps and four metal snaps. They were sold in both youth and adult sizes and come in black/gray and white/gray color combinations. The Nike Swoosh trademark is printed on the outside of the chin cup and DRI-FIT™ is printed on the foam liner. "Made in China" and one of the following four style numbers is printed on the inside of the strap: FA0016 046, FA0016 130, FA0021 046, or FA0021 130.	Sporting good stores nationwide and on the firm's Web site www.Nike.com	April 2006 through October 2007	http://www.cpsc.gov/cpsc/pub/prerelease/prhtml08/08081.html			
storage racks with canvas totes	The storage rack can tip over, posing an entrapment and suffocation hazard to young children.	Consumers should immediately stop children from using the recalled storage racks and contact Jetmax International to receive a free repair kit that adds stability to the base.	The storage rack is wooden with three levels and nine removable canvas totes. There are wooden handles on each side of the rack. The boy's storage rack has natural color wood with red, yellow, green, and navy canvas totes. The girl's storage rack has white colored wood with pink, yellow, lime, and purple canvas totes. Sold under the brand "Home Trend Kids 9 Canvas Bin Boy's and Girl's Organizers."	Wal-Mart stores nationwide and Ollie's stores nationwide	August 2004 through July 2005 and July 2006 through June 2007	http://www.cpsc.gov/cpsc/pub/prerelease/prhtml08/08085.html			

Dangerous and Recalled Products - Transmittal Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
Visual Presenters (sold as Image Presentation Cameras by Epson)	Improperly installed fluorescent top lights in the presenter can overheat, posing a fire hazard.	Consumers should stop using the recalled visual presenters immediately and contact Elmo USA for all models except Epson. All Epson owners should contact Epson. Consumers with recalled units will receive a free inspection and repair.	Visual presenters capture images to LCD panels, LCD projectors and TV monitors. The recall includes presenters sold under the ELMO, Epson, Doar Communications, Vtel and Tandberg brand names. The presenters were manufactured between December 1993 and December 2003. The manufacturer information is located on the side, rear and bottom of the main body of the following ELMO model numbers, EV-500AF, EV-400AF, EV-6000AF, EV-8000AF, HV-5000XG, HV-7000SX, HV-8000SX, EV-4400AF, HV-5100XG and Epson model ELPDC02.	Elmo dealers, office supply stores and other retailers nationwide	December 1993 to June 2006	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08098.html			
Shaving Paint Brushes	Surface paint on the brush handles can contain excessive levels of lead, violating the federal lead paint standard.	Consumers should stop using the brushes immediately and contact Discount School Supply to receive a free replacement brush set.	The recall involves a set of six "shaving-style" brushes, which are about 4-inches long. The brushes' handles are painted blue, purple, orange, yellow, lime green, and pink. The item number #SHVBRSH is printed on the product's packaging. Brush sets with handles in brown, dark blue, red, green, blue, and black are not included in this recall. The recalled brushes were also included with the "BioColor® Foam Paint Starter Kit" and "Colorations® Foam Paint Starter Kit."	Discount School Supply's catalog and Web site	May 2004 through August 2007 The BioColor® kits were sold from May 2004 through June 2006 and The Colorations® kits were sold from July 2006 through August 2007.	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08090.html			
Metalux Fluorescent Shop Lights	When the two prongs on the plug's electrical cord are touched simultaneously while lamps are installed, the light can pose an electric shock hazard to consumers.	Consumers should stop using the light fixture immediately and uninstall it according to instructions posted at www.cooperlighting.com . The fixture should be returned to the place of purchase for a full refund or credit.	This recall involves the Metalux fluorescent shop lights Model 9240. Only date codes between December 1, 2006 ("344 06") and September 14, 2007 ("257 07") are included in this recall. The date code format includes the day and the year. For example, "344 06" refers to the 344th day of year 2006, or December 1, 2006. The model number and date code can be found on the packaging and on labels adhered to the fixture housing.	Major home center and hardware stores nationwide	January 2007 to October 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08089.html			
"Power Bolt" Y-Frame and Ultimate Y-Frame Adjustable Pitchbacks	The upper portion of the frame can collapse after both locking pins are removed, posing a laceration hazard.	Consumers should stop using the product immediately and contact Dick's Sporting Goods to receive a free repair kit.	This recall involves the Power Bolt Y-Frame Pitchback and Y-Frame Ultimate Pitchback. The products' Y-shaped metal frames have attached netting which will return a thrown ball to the user. The upper portion of the frame is adjustable to allow a variety of rebound angles.	Dick's Sporting Goods retail stores nationwide and on its Web site.	Y-Frame Pitchback was sold from November 2002 to July 2007. The Power Bolt Y-Frame Ultimate Pitchback was sold from February 2005 to July 2007.	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08102.html			
Performax and Wilton 10" Sliding Miter Saws	The saw handle's switch can fail, causing the saw to smoke, spark, and trip circuit breakers, and disable the safety brake. The saw also can keep operating unless the unit is unplugged, posing a laceration hazard to consumers.	Consumers should immediately stop using these saws and call WMH to receive a replacement miter saw or a full refund.	The recall includes Performax model number 90206 and Wilton model number 34570 10-inch sliding miter saws with date code/serial numbers ranging from W062505 to W070405. The model, date code/serial numbers are printed on a black label on the motor housing of the saw.	Home centers and hardware retailers nationwide	August 2006 through March 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08100.html			

Dangerous and Recalled Products - Transmittal Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
Nordic Track and Reebok Inversion Benches	The ankle clamp mechanism can release unexpectedly, posing a fall hazard to consumers.	Consumers should stop using the inversion benches immediately and contact the firm to receive a free repair kit.	The recalled inversion benches invert a user by securing the ankles in a locking device and rotating the bench. The Nordic Track bench is model number 831.14595.0 and the Reebok bench is model number RBBE1996.0. The model number is located under the seat of the bench.	Sporting goods stores nationwide	September 2006 through January 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08109.html			
Bowflex® Ultimate 2 Home Gyms	The fasteners used to secure the rod box to the frame of the equipment can come loose, allowing the resistance rods or rod box to separate and strike the user or a bystander.	Consumers should immediately stop using the recalled home gym until a repair kit is installed. Registered owners are being sent a free repair kit. Owners who have not received a repair kit by the end of the first week in January 2008 should contact the firm.	The recalled home gyms are equipped with pulleys, resistance rods, and other equipment, which allow the user to perform a variety of exercises. "Bowflex Ultimate 2" is written on the vertical part of the frame.	Specialty fitness retailers nationwide and through direct sales	June 2005 to August 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08520.html			
Oscillating Ceramic Heaters	The heaters can overheat, smoke, or ignite which could pose a fire hazard to consumers	Consumers should immediately stop using the heaters and return them to the nearest Menards' store for a full refund	This recall involves 1500 watt oscillating ceramic heaters model EB38005. The heater has a white plastic housing with the name "Heat-Wave" in black on its top. A label on the bottom of the product contains the model and the control number "ETL 3090262."	Menards' stores nationwide	September 2006 through March 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08115.html			
The First Years 3-in-1 Flush and Sounds Potty Seats	Decorative plaque inserted into the back of the potty seat could have orange paint that contains excessive levels of lead, violating the federal lead paint standard.	Consumers should keep these recalled items away from young children and should contact RC2 to receive a permanent clear protective cover that covers the plaque. The unit can still be used as a potty seat.	The recall involves the First Years 3-in-1 Flush and Sounds potty training seats. Each seat has either a yellow chair with a green removable seat and a purple lift out-pot or a blue chair with a white removable seat and green lift out-pot. The words "100 Acre Wood" are molded on the chair back. The plaque inserted into the back of the seat contains molded Winnie the Pooh and Tigger characters.	Mass and specialty retailers nationwide	April 2006 through August 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08119.html			
TV Stands	The plastic feet of the TV stand can crack or break. The stability of the stand can be reduced, increasing the risk of a TV tipping-over.	Consumers should contact Sauder to receive free replacement feet. Until the feet are replaced, consumers should be sure the TV is placed at least 1/2 inch back from the front edge of the TV shelf.	The recalled TV Stand measures 23 inches (h) x 43 1/4 inches (w) x 17 1/2 inches (d) with a brushed maple finish. The stand has black, wrought-iron legs and a lower shelf with a pull-out drawer. The model number (402806) and UPC (0004266643392) are located on the product's carton and instructions. The top shelf does not have a raised front edge.	A limited number of Wal-Mart stores	Aug-07	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08525.html			
WEE CHI Ceramic Hairstyling Irons	The iron's "on/off" switch was installed incorrectly. When the iron is plugged in and switch is in the "off" position, the iron remains "on," which could pose fire and burn hazards.	Consumers should stop using the product immediately and contact the firm to return the product for a full refund or replacement iron. Farouk Systems is directly notifying all distributors and retailers.	The recalled hairstyling iron is black and measures 9.5 inches long. "CHI" is printed on the iron in red lettering. Date code 0306 or 0507 is embossed on the inside of the paddle.	Professional beauty supply distributors and beauty salons nationwide	April 2006 through September 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08124.html			
Eclipse® 1175e Elliptical Trainers	The cranks that connect the foot platforms to the rear wheel of the machine can break during exercise, posing a fall hazard to consumers.	Consumers should stop using the recalled elliptical trainers immediately and contact Fitness Quest for a free replacement elliptical machine or a credit towards the purchase of another Fitness Quest exercise machine.	This recall involves the Eclipse® 1175e elliptical trainers. The elliptical trainer is a cardiovascular exercise machine. The machine has two foot platforms attached to a wheel at the rear of the machine. Each machine has "1175e" stamped on an oval decal located on the side of the wheel housing.	Sports Authority, Modell, Dunhams, JC Penney stores and other retailers nationwide	September 2006 to October 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08126.html			

Recalled and Recalled Products - Transmittal Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
Specialized Bicycle Helmets	The helmets fail testing required under CPSC's safety standard for bicycle helmets. This can pose a head injury hazard to riders in a fall.	Consumers should stop using the recalled helmet immediately and return it to an Authorized Specialized Retailer to receive a free replacement or a full refund	This recall involves the Specialized helmets, model 2D. Model "2D" is printed on the sides of the helmet in the rear. The helmets were sold for men and women in matte black, white, silver, blue, pink, and team colors.	Specialized through its authorized retailers and online stores	between July 2007 and October 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08138.html			
Giant Measuring Chart	The paint on the grow chart contains excess levels of lead, violating the federal lead paint standard.	Consumers should stop using the chart immediately and contact Discount School Supply to receive a credit or refund.	The Giant Grow Chart measures a child's growth with a giant yellow ruler-shaped plastic chart. The grow chart also has a picture of a bean stalk painted on it from top to bottom.	Discount School Supply catalogs and the company's Web site	August 2000 through August 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08528.html			
Honda Walk-Behind Lawn Mowers	The cutting blades could rotate under power when the control lever is released. The lawn mowers do not comply with mandatory federal safety standards for lawn mowers. The spinning blade poses a serious laceration hazard to consumers.	Consumers should stop using these recalled lawn mowers immediately and contact any Honda Lawn and Garden dealer for a free repair. Registered owners will be mailed a direct notice.	The recall involves Honda walk-behind lawn mowers with model numbers HRB217HXA, HRX217HXA and HRX217HMA. The model and serial number are printed on a label located on the upper rear of the mower deck. The lawn mowers are dark gray with a red fan cover. The following serial numbers are included in the recall: Models Serial Numbers HRB217HXA All HRX217HXA and HRX217HMA 1000001 - 1513628	Honda Lawn and Garden dealers and The Home Depot stores nationwide	January 2003 through November 2007	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08140.html			
Remington and McQuay "ComfortPac" Air Conditioners and Heat Pumps	Wires in the heater element can overheat and spark, posing a smoke and fire hazard to consumers.	McQuay has been directly notifying businesses. Building managers or owners who have not been contacted by McQuay should stop using the recalled units immediately and contact the firm for a free repair kit.	The recall involves the Remington and McQuay "ComfortPac" Packaged Terminal Air Conditioners (PTAC) and Packaged Terminal Heat Pumps (PTHP) commonly installed in hotels, nursing homes, and other commercial locations. These "B" and "B+" vintage electric heat units come in size 12 (12,000 BTU) and size 15 (15,000 BTU). The model numbers included in the recall are: PTAC12B208 KXBA and KXCA PTAC12B265 MXBA and MXCA PTHP12B208 KXBA and KXCA PTHP12B265 MXBA and MXCA PTAC15B208 KXBA and KXCA PTAC15B265 MXBA and MXCA PTHP15B208 KXBA and KXCA PTHP15B265 MXBA and MXCA The model numbers are printed on the product identification plate, which is located underneath the front cover below the control box. The recalled units also have the following numbers on the power cord: 105575703 (208/230V) and 105575803 (265V).	McQuay sales representatives and distributors nationwide	November 2001 through June 2006	http://www.cpsc.gov/cpsc/pub/prereel/prhtml08/08530.html			

Recalled and Recalled Products - Transmittal Form - Fourth Quarter, 2007

<u>Product</u>	<u>Hazard</u>	<u>Remedy</u>	<u>Description</u>	<u>Distributor</u>	<u>Market Date</u>	<u>Web Link</u>	<u>Not Present</u>	<u>Present</u>	<u>How Abated</u>
DEWALT Cordless Drills	The trigger switch of the cordless drill can overheat, posing a fire hazard to consumers	Consumers should stop using the drills immediately and contact DEWALT for the location of the nearest service center to receive a free inspection and, if necessary, free repair.	<p>This recall involves DEWALT individual cordless drills listed below:</p> <p>Model Number Description Date Codes DC920 Heavy-Duty XRP™ 1/2" (13mm) 18 Volt Cordless Drill/Driver 200723 through 200742 DC930 Heavy-Duty XRP™ 1/2" (13mm) 14.4 Volt Cordless Drill/Driver 200625 through 200746 DC935 Heavy-Duty XRP™ 1/2" (13mm) 14.4 Volt Cordless Hammerdrill/Drill/Driver 200627 through 200746 DC936 Heavy-Duty XRP™ 1/2" (13mm) 14.4 Volt Cordless Hammerdrill/Drill/Driver 200635 through 200746 DC940 Heavy-Duty XRP™ 1/2" (13mm) 12 Volt Cordless Drill/Driver 200635 through 200746</p> <p>The model number is printed on a sticker on the side of the unit. The date code is embossed on the bottom of the unit. Units stamped with an "M" following the date code have been repaired and are not included in this recall. The packaging of repaired drills has a green dot sticker near the UPC label.</p>	Wholesale distributors and retailers	June 2006 through December 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08143.html			
World Dryer and Bradley Brand Hand and Hair Dryers	Some of the nozzles on these dryers are not grounded. If an electrical component comes into contact with an ungrounded nozzle, it can pose a shock hazard to consumers.	World Dryer has been contacting facilities utilizing these dryers. Facilities that have the recalled dryers will receive a free repair kit. Consumers and facility managers that have not been contacted should call World Dryer with serial and model number to determine if the dryer is included in this recall.	The World Dryer and Bradley brand hand and hair dryers are wall-mounted dryers with nozzles protruding from the front that may be either recessed or surface mounted. The dryers are used primarily in rest rooms and locker rooms in public and commercial buildings.	Industrial and electrical distributors and supply houses nationwide	June 2005 through April 2007	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08531.html			
Counterfeit Circuit Breakers labeled as "Square D"	The recalled circuit breakers labeled "Square D" have been determined by Square D to be counterfeit and can fail to trip when they are overloaded, posing a fire hazard to consumers.	Consumers should contact NABCO to determine if the breaker they have is counterfeit and to arrange for a free inspection and replacement or refund if necessary.	The counterfeit circuit breakers are black and are labeled as Square D QO-series models 110, 115, 120, 130, 210, 215, 220, 225, 230, 235, 240, 250, 260, 280, 1515, 1520, 2020, 2125, 315, 340, 350, 360, and 3100. Actual Square D circuit breakers have (a) the amp rating written on the handle in white paint on the front of the breaker; (b) the Square D insignia molded onto the breaker side, and; (c) a yellow chromate mounting clip with half of the top of the clip visible. If your breaker, labeled as Square D, does not match this description, it could be counterfeit.	NABCO, electrical distributors, and retailers nationwide	March 2003 through April 2006 f	http://www.cpsc.gov/cpscpub/prereel/prhtml08/08151.html			